

Section 6 - 2

List of Contents

1.	Quality category of the test equipment.....	1
2.	Tools and auxiliary equipment.....	1
2.1	Recommended tools and test equipment.....	1

1. Quality category of the test equipment


Test equipment to be used : Multimeter (V/A/OHM) with an accuracy of 1 %.

2. Tools and auxiliary equipment


2.1 Recommended tools and test equipment

In addition to the general tools, which every service technician has in his tool box, the following equipment is required for the service:

Auxiliary Equipment	Spare Part Number	Application
Grounding strap	CM+9.9999.0830.0	Replacement of PCBs / EPROMs
Spring scale 100N		Torque of the racks
Isoflex Topas NB52	CM+9.9999.9247.0	
Ballistol	CM+9.9999.9136.0	
AMP extraction tool	CM+9.9999.1005.0	Replacement of pins and sockets in plugs and couplings
Service key	CM+9.9999.0907.0	Overriding of the cover switch



AMP extraction tool



Service key